


AD-A169 557 PRELIMINARY MATERIAL TESTING OF CERAMIC AND WOOD(U) AIR 1/1
FORCE WEAPONS LAB KIRTLAND AFB NM R W NETHERS ET AL.
MAY 86 AFWL-TN-85-47

UNCLASSIFIED

F/G 13/3

NL





MICROCOPY RESOLUTION TEST CHART
NATIONAL BUREAU OF STANDARDS-1963-A

AD-A169 557

**PRELIMINARY MATERIAL TESTING OF CERAMIC
AND WOOD**Raymond W. Nethers
David W. Metzger

May 1986

DTIC
ELECTE
S JUL 11 1986 **D**
AL D

Final Report

Approved for public release; distribution unlimited.

DTIC FILE COPY

AIR FORCE WEAPONS LABORATORY
Air Force Systems Command
Kirtland Air Force Base, NM 87117-6008

86 7 11 029

This final report was prepared by the Air Force Weapons Laboratory, Kirtland Air Force Base, New Mexico, under Job Order 12091501. Mr. Raymond W. Nethers (NTAO) was the Laboratory Project Officer-in-Charge.


When Government drawings, specifications, or other data are used for any purpose other than in connection with a definitely Government-related procurement, the United States Government incurs no responsibility or any obligation whatsoever. The fact that the Government may have formulated or in any way supplied the said drawings, specifications, or other data, is not to be regarded by implication, or otherwise in any manner construed, as licensing the holder, or any other person or corporation; or as conveying any rights or permission to manufacture, use, or sell any patented invention that may in any way be related thereto.

This report has been authored by employees of the United States Government. Accordingly, the United States Government retains a nonexclusive, royalty-free license to publish or reproduce the material contained herein, or allow others to do so, for the United States Government purposes.

This report has been reviewed by the Public Affairs Office and is releasable to the National Technical Information Service (NTIS). At NTIS, it will be available to the general public, including foreign nations.

If your address has changed, if you wish to be removed from our mailing list, or if your organization no longer employs the addressee, please notify AFWL/NTAO, Kirtland AFB, NM 87117 to help us maintain a current mailing list.

This technical report has been reviewed and is approved for publication.



RAYMOND NETHERS
Project Officer



ALBERT B. GRIFFIN
Acting Chief, Test Operations Branch

FOR THE COMMANDER



PHILIP J. MESSURI
Major, USAF
Chief, Aircraft & Missiles Division

DO NOT RETURN COPIES OF THIS REPORT UNLESS CONTRACTUAL OBLIGATIONS OR NOTICE ON A SPECIFIC DOCUMENT REQUIRES THAT IT BE RETURNED.

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE

REPORT DOCUMENTATION PAGE

1a. REPORT SECURITY CLASSIFICATION Unclassified			1d. RESTRICTIVE MARKINGS	
2a. SECURITY CLASSIFICATION AUTHORITY			3. DISTRIBUTION/AVAILABILITY OF REPORT Approved for public release; distribution unlimited.	
2b. DECLASSIFICATION/DOWNGRADING SCHEDULE				
4. PERFORMING ORGANIZATION REPORT NUMBER(S) AFWL-TN-85-47			5. MONITORING ORGANIZATION REPORT NUMBER(S)	
6a. NAME OF PERFORMING ORGANIZATION Air Force Weapons Laboratory		6b. OFFICE SYMBOL (If applicable) NTAOP		7a. NAME OF MONITORING ORGANIZATION
6c. ADDRESS (City, State and ZIP Code) Kirtland Air Force Base, NM 87117			7b. ADDRESS (City, State and ZIP Code)	
8a. NAME OF FUNDING/SPONSORING ORGANIZATION		8b. OFFICE SYMBOL (If applicable)		9. PROCUREMENT INSTRUMENT IDENTIFICATION NUMBER
8c. ADDRESS (City, State and ZIP Code)			10. SOURCE OF FUNDING NOS.	
			PROGRAM ELEMENT NO. 64747F	PROJECT NO. 1209
			TASK NO. 15	WORK UNIT NO. 01
11. TITLE (Include Security Classification) PRELIMINARY MATERIAL TESTING OF CERAMIC AND WOOD				
12. PERSONAL AUTHOR(S) Nethers, Raymond W. and Metzger, David W.				
13a. TYPE OF REPORT Final Report		13b. TIME COVERED FROM 1 Feb 85 to May 85		14. DATE OF REPORT (Yr., Mo., Day) 1986 May
15. PAGE COUNT 12				
16. SUPPLEMENTARY NOTATION				
17. COSATI CODES			18. SUBJECT TERMS (Continue on reverse if necessary and identify by block number)	
FIELD	GROUP	SUB. GR.		
13	03		Electrical Breakdown, Insulator Flashover, Standoff	
20	03		Voltage, Insulator, Isolation Material	
19. ABSTRACT (Continue on reverse if necessary and identify by block number)				
Results of preliminary tests of various construction materials subjected to high voltage electrical discharge are reported along with test conduct. Two high voltage construction materials, a wood post and a ceramic insulator, were tested. As a corollary a typical wood fastening system, similar to a TRESTLE joint, was tested. Flashing over of the ceramic insulator caused no damage, while flashing over of the wood at high overvoltages causes considerable damage. Fastening systems in sparse patterns does not appear to change the standoff voltage of the wooden beam used as an insulator.				
20. DISTRIBUTION/AVAILABILITY OF ABSTRACT UNCLASSIFIED/UNLIMITED <input type="checkbox"/> SAME AS RPT. <input checked="" type="checkbox"/> DTIC USERS <input type="checkbox"/>			21. ABSTRACT SECURITY CLASSIFICATION Unclassified	
22a. NAME OF RESPONSIBLE INDIVIDUAL Mr. Raymond W. Nethers			22b. TELEPHONE NUMBER (Include Area Code) (505) 844-3412	22c. OFFICE SYMBOL NTAOP

DD FORM 1473, 83 APR

EDITION OF 1 JAN 73 IS OBSOLETE.

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE

INTRODUCTION

This note presents the results of preliminary tests of various construction materials subjected to high voltage electrical discharge. The purpose of these tests was to determine the high voltage breakdown point of these materials. Of the most commonly used materials in high voltage construction, a ceramic insulator and a wood post were first to be tested.

As a corollary a typical wood fastening system, similar to a TRESTLE wooden joint, was the second test. The purpose of the wood joint test was to investigate the effects of the wooden beam fasteners used in the TRESTLE structure on the electrical breakdown strength of the wood beams and the effect of the breakdown on the physical strength of the joint.

The tests were performed using negative voltages only as this polarity provides the highest standoff voltages.

TEST CONDUCT

CERAMIC INSULATOR

The twenty stage marx Ferranti Impulse Generator (FIG) was configured to produce the waveshape recommended for the Trailing Wire Antenna (TWA) tests [risetime (10-90 percent) 1.7 μ s, decay time (50 percent) 37 μ s]. A spare ceramic insulator for the FIG was selected for the test. This insulator is of English manufacture and no information is available for it although it must withstand about 400 kV for its use in the FIG. The insulator is 45-in high and 17-in in dia.

The insulator was connected to the FIG as shown in Fig. 1. Most of the data was taken with a 2000 Ω copper sulfate current-limiting resistor in series with the insulator, but some was taken with this resistor omitted.

The up-down method was used to determine the 50 percent breakdown voltage and sigma, the standard deviation. This method requires at least 30 test shots to gather sufficient data for results.



By	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A-1	




Figure 1. Insulator test setup.

WOOD POST

A 6 by 6-in fir wood post 5.6 ft long with steel mounting brackets on both ends was selected for this test. This post had been painted with white enamel, but exposure to the weather for some years had caused some minor splits and cracks. The post also had a high pitch content and high density.

The first test was with the generator connected to the top steel mounting bracket. The current-limiting resistor, shown in Fig. 1, was not used for any of the wood post tests. The second test was with the top steel bracket removed and a 19-in-dia metal donut anticorona ring mounted to the top of the post. The third test was with a larger 30-in-dia anticorona ring fashioned from copper mesh and an inflated tire inner tube. For the fourth test, the FIG was connected to a pointed 3/8-in steel rod that was placed in a hole about 4-in deep drilled in the top of the post.

The up-down test method was not used for these tests due to the probability of tracking occurring on or in the wood which would prevent the conductivity of the post from remaining constant over the period of the tests.


After initial testing, a number of overvoltage shots were taken. This was done to determine the effect of large overvoltages on the wood.

TRESTLE WOOD JOINT


A beam was fastened to another beam as shown in Fig. 2. Two different sizes of metal rings were installed in the joint as well as the four bolts to simulate a typical TRESTLE beam joint.

A 30-in anticorona ring fashioned from copper mesh and an inner tube was mounted on top of the beam for connection to the FIG. An attempt was made to use the standard up-down 50 percent test method, but the repeatability of the data made this method unnecessary.

The first test was conducted with four wood bolts in place and no split rings. The second test was conducted with four wood bolts and four split rings in place. The third test was conducted with four metal bolts and four split rings in place.



(a) Test setup with anticorona ring.



(b) Metal bolts.

Figure 2. TRESTLE wood joint test setup.

RESULTS

CERAMIC INSULATOR

The breakdown time for the ceramic insulator varied from 3 to 8 μ s with the most typical time being about 4 μ s. The 50 percent breakdown voltage was calculated to be 580 kV and sigma was calculated to be 62,741 V.

During the ceramic insulator test the decay time of the FIG varied from 30 to 27.5 μ s for 50 percent decay. This was probably due to temperature variation as most of the pulser load consists of copper sulfate solution resistors which are very sensitive to temperature variation.

WOOD POST

Seven shots were made for the first wood post test with the steel bracket mounted on top of the beam. Five flashovers were observed.

The breakdown voltages with the resistor were 608, 540, and 501 kV. The time delay for breakdown was from incomplete risetime to 5 μ s. For all breakdowns, the arc tracked on the surface of the post in a new position and peeled off a few small splinters. No structural damage was observed.

Four shots were made with the small 10-in-dia donut on top of the post. Two flashovers were observed at 529 kV for both. The time to breakdown was less than 1 ms. As for this test, no structural damage was observed and only minor splinters were loosened by surface tracking.

Seven shots were made with the large 30-in-dia donut attached to the post. Two flashovers were observed at 814 and 760 kV. Times were 5 and 10 μ s. Once again, only a few small splinters were ejected.

Five shots were made with a pointed rod installed in a vertical hole drilled in the top of the post. Four shots flashed over at 936, 707, 576, and 557 kV. Time to flashover varied from incomplete risetime to less than 1 ms. The flashovers for this test were through the wood. No structural damage or burning was apparent. The only sign of flashover was a slight smell of ozone around the top of the post.

Ten overvoltage shots (nominal 1.5 MV) were taken. These caused the corners of the post to be ejected in large 1 by 1-in shards.

TRESTLE WOOD JOINT

The flashover voltage for the joint with wooden bolts and no split rings was 538 kV; with split rings was 518 kV. The flashover voltage for the joint with metal bolts and split rings was 540 kV.

The time to breakdown was approximately 1 to 2 μ s. The breakdown usually occurred just before the pulser output wave shape reached its peak value.

The flashovers tracked on the surface of the wood and through the split rings. Voltages just above flashover value caused no structural damage.

One pulser shot was made at 120 kV charge voltage (nominal 1.5 MV output). This shot caused considerable structural damage as a 1 by 1-in shard was ejected (Fig. 3).


CONCLUSION

Flashing over the ceramic insulator did not harm it. The wood post withstood low voltage flashovers with no structural damage, but when shots were taken with a high overvoltage, major structural damage resulted.

Use of a large 30-in-dia field shaping donut seems to increase the breakdown voltage level approximately 40 percent for a wooden post.

The results of the TRESTLE wood joint test shows that metal rings and bolts in sparse patterns have little effect on the standoff voltage of the wooden beam used as an insulator.

In general, a large overvoltage can cause extensive structural damage to wood beams; however, an overvoltage slightly above the standoff voltage of the wood seems to cause only minor damage with surface tracking.



(a) Damage to upper part of post.



(b) Damage to lower part of post.

Figure 3. Damage to TRESTLE wood joint post.

END

DTric

8-86